

ASSEMBLE INSTRUCTIONS 5008





| ardwa |
|-------|
| 1 |
| 1 |
| 1 |
| |
| 191 |
| e |
| 100 |

| 4 | ယ | 2 | - |
|-------------|--------------------|-----------|--------------|
| 0 | 0 | | |
| Flat Washer | Spring Washer 8pcs | Bolt Bolt | "L" Wrenches |
| 8pcs | 8pcs | 8pcs | lpcs |